



Insulation: Not to be above the bottom edge of the top chord of I-joist or within the top 2" of 2x Joist.